



STATE OF VERMONT
 Division for Historic Preservation
 Montpelier, VT 05602

HISTORIC SITES & STRUCTURES SURVEY
 Individual Structure Survey Form

SURVEY NUMBER: 32 Marble Ave.
NEGATIVE FILE NUMBER: 77-A-276
UTM REFERENCES: Zone/Easting/Northing
U.S.G.S. QUAD. MAP:
PRESENT FORMAL NAME:
ORIGINAL FORMAL NAME: Joseph Robinson house
PRESENT USE: 2-family
ORIGINAL USE: residence
ARCHITECT/ENGINEER:
BUILDER/CONTRACTOR:
PHYSICAL CONDITION OF STRUCTURE:
 Excellent Good
 Fair Poor
THEME:
STYLE:
DATE BUILT: ca. 1884

COUNTY: Chittenden
TOWN: Burlington
LOCATION: 32 Marble Ave.
COMMON NAME:
FUNCTIONAL TYPE: dwelling
OWNER: Valleff & Dorothy Belatski
ADDRESS: 32 Marble Ave.
ACCESSIBILITY TO PUBLIC:
 Yes No Restricted
LEVEL OF SIGNIFICANCE:
 Local State National

GENERAL DESCRIPTION:
 Structural System
 1. Foundation: Stone Brick Concrete ^{faceted} Concrete Block
 2. Wall Structure
 a. Wood Frame: Post & Beam Balloon
 b. Load Bearing Masonry: Brick Stone Concrete Concrete Block
 c. Iron d. Steel e. Other:
 3. Wall Covering: Clapboard Board & Batten Wood Shingle
 Shiplap Novelty Stucco Sheet Metal Aluminum
 Asphalt Shingle Brick Veneer Stone Veneer
 Bonding Pattern: Other: asbestos
 4. Roof Structure
 a. Truss: Wood Iron Steel Concrete
 b. Other:rafter
 5. Roof Covering: Slate Wood Shingle Asphalt Shingle
 Sheet Metal Built Up Rolled Tile Other:
 6. Engineering Structure:
 7. Other:
 Appendages: Porches Towers Cupolas Dormers Chimneys
 Sheds Ells Wings Other:
 Roof Style: Gable Hip Shed Flat Mansard Gambrel
 Jerkinhead Saw Tooth With Monitor With Bellcast
 With Parapet With False Front Other:
 Number of Stories: 2
 Number of Bays: 3 x 2
 Entrance Location: side hall
 Approximate Dimensions:

THREAT TO STRUCTURE:
 No Threat Zoning Roads
 Development Deterioration
 Alteration Other:

LOCAL ATTITUDES:
 Positive Negative
 Mixed Other:

ADDITIONAL ARCHITECTURAL OR STRUCTURAL DESCRIPTION:

Massing - front gable orientation - shed-roofed, 1-story. Front porch which wraps around to the side and incorporates a 1 bay ell which continues around the rear. Rear wings.

Fenestration - some 2 over 2 sashes, some double hung. Strip molded heads.

Door - plain surround strip molded heads. Wood door with glass panel upper section, horizontal panels below. Side door is Italianate with pair of long glass panels.

Enrichments - bands of red imbricated roof slates as well as imbricated and rectangular grey slates. Roof slates on houses #35, 37 and 42 are identical.


RELATED STRUCTURES: (Describe)

STATEMENT OF SIGNIFICANCE:

Joseph Robinson is listed in the 1886 Directory as living here. He was a foreman in the Burlington Manufacturing Co. He is also listed in the Burlington City Census in 1885.

REFERENCES:

MAP: (Indicate North In Circle)



SURROUNDING ENVIRONMENT:

Open Land Woodland
Scattered Buildings
Moderately Built Up
Densely Built Up
Residential Commercial
Agricultural Industrial
Roadside Strip Development
Other:

RECORDED BY:

Adele Cramer

ORGANIZATION:

VT Division for Historic Preservation

DATE RECORDED:

10/7/77